



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: April 6, 2007

Supervisor 

Mine Name: Quarry Antone
Operator Name: Utah Portland Cement

Permit number: M0450021
Inspection Date: 03/15/2007
Time: 11:00 AM

Inspector(s): Tom Munson
Other Participants: None
Mine Status: INA

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)	X	X	
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other			

Purpose of Inspection:

To determine the status of the operation.

Directions to Site:

Easy access from paved Grantville road.

Inspection Summary:

Site shows no signs of recent activity. Vegetation is taking over road access and perimeter of site. There is a explosive magazine fenced off by chain link fence.

Conclusions and Recommendations:

There is a gate that blocks access to the site. Its been broken down and is not locked. It seems that this gate should be repaired and the site secured. If there are explosives in the magazines they should removed, as the site appears abandoned.

Inspector's Signature  Date: April 9, 2007

tm

cc:

Operator

Attachment: Photos



QUARRY ANTONE
3/15/2007
M450021

← FENCED
EXPLOSIVE MAGAZINES?



GATE TO QUARRY



HISTORIC HIGH WALL